

9000 - PORTRAIT

MR - W^m MARSHALL -

SEPT. 20 '16

9001. - E8950 - SOLE CEMENTING MACH.

MOH - A - FRONT & RIGHT -

SCA

SEPT. 25 - '16

9002. - E8951 - SOLE CEMENTING MACH.

MOH - A - FRONT & LEFT.

SEPT. 25 - '16

9003-. PORTRAIT-

MR. E. J. RAY.

SEPT-16-'16

9004-. GOODYR' OUTSOLE RAPID LOCK - ROS

STITCH - MOD. B. FLOOR TYPE - WITH

KEROSENE GENERATOR - OCT-13-'16

9005.- GR - OUTSOLE RAPID LOCK STITCH

MOD. C. FLOOR TYPE - WITH KEROSENE

GENERATOR - ROS - OCT-13-'16

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

neg - missing

See copy 9511

9006 - USMC - STAINING TRAILING

FRONT & RIGHT

USN

OCT-25-16

9007 - E8988 - SHOE REPAIR OUTFIT - TYPE P - STYLE 25 - ROP

FIN - BUF & SINGLE SCOUR -

FRONT & R - 9 FC -

OCT-25-16

9008 - E8989 - SHOE REP. OUTFIT - TYPE P - STYLE 28 - ROP

FIN. - BUF. WITH DOUBLE SCOUR -

FRONT & R - 10 FC -

OCT-25-16

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

9009- E8990- SHOE REPAIR OUTFIT- TYPE P- STYLE 15- ROP

BUF. & FIT. WITH SINGLE SCOUR- STITCHER- R.H

FRONT & R- 97c.

OCT-26-'16

9010- E8991- SHOE REP. OUTFIT- TYPE P- STYLE 12- ROP

BUF. & FIT. WITH SINGLE SCOUR- TRIM- STITCH- R.H.

FRONT & R- 127c.

OCT-26-'16

9011- E8992- SHOE REP. OUTFIT- TYPE P. STYLE 26- ROP

FIT. BUF. WITH DOUBLE SCOUR- STITCHER- R.H.

FRONT & R- 137c.

OCT-27-'16

9012-E8993-SHOF REP. OUTFIT- TYPE P- STYLE 23- ROP

FIN. BUF. WITH SINGLE SCOUR- STITCHER- R.H.

FRONT & R- 127C.

OCT-27-'16

9013- DROP FORGE NIES ORL- NO. 71

FINISHING-

FOR ENGLAND-

NOV-3-'16

9014- DROP FORGE NIES- ORL- NO. 71

FINISHING-

FOR ENGLAND-

NOV-3-'16

9015-DROP FORGE PIES. ORL- #71

FINISHING

FOR ENGLAND.

NOV-3-'16

9016-DROP FORGE PIES. ORL- #71

FINISHING

FOR ENGLAND.

NOV-3-'16

9017-ECONOMY INSOLE STITCHING MACH-EIS-

SHOWING BUSHING OF NEEDLE BAR +

PRESSER FOOT HOLES.

NOV-3-'16

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

9018-. ATLAS LEVELING MACH. AL

FRONT + RIGHT - MOD. A.

OCT-17-'16

9019-. STEAM DRIVEN CENTRIFUGAL PUMP.

NOV-7-'16

9020-. DROP FORGE PIES. ORL-71

ROUGHING

FOR ENGLAND.

NOV-7-'16

9021 - DROP FORGE DIE ORL-#71

ROUGHING -

FOR ENGLAND -

NOV-7-'16

9022 - DROP FORGE DIE ORL-#71

ROUGHING

FOR ENGLAND -

NOV-7-'16

9023 - GREEN HOUSE - INTERIOR

MR. WINSLOW'S -

NOV-8-'16

9024 - GREEN HOUSE - INTERIOR -
MR. WINSLOW'S

NOV. 8 - '16

9025 - GREEN HOUSE - INTERIOR -
MR. WINSLOW'S

NOV. 8 - '16

9026 - BUFFING MACH. - MOD. G.
SHOWING MOTOR.

NOV. 15 - '16

9027 - GOODYEAR UPPER STAPLING MACH.
MODEL B. HEAD. FOR PURPOSE OF
ENGRAVER. - GUS - NOV-6-'16

9028 - HIGH STAND FINISHING SHAFT
MODEL R - MOTOR DRIVEN FSR
Front + Right NOV-16-'16

9029 - USMC. EMBOSSING MACH.
MODEL C. MOTOR DRIVEN UE
Back + Right NOV-16-'16

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

9030 - CREST HEEL BLACKING
MOD. B. MOTOR DRIVEN. CB

NOV-16-'16

9031 - USMC - LASTING MACH. No. 6.
MOTOR DRIVEN - LM

FRONT + LEFT NOV-16-'16

9032 - IMPROVED GEARLESS SOLE
CUTTING MACH. MOD. S - G, S C

9 FT. MOTOR DRIVEN - NOV-16-'16

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

FRONT + R.

9033-- PORTRAIT

MR. DANIEL LOW

NOV-16-'16

9034-- G.R. OUTSOLE RAPID LOCKSTITCH C. ROS
ELEC. HEAT

NOV-17-'16

9035-- SHOE REPAIR OUTFIT STYLE 29- G. RO
COMBINATION FIN. & BUFT SCOUR, WITH SINGLE
BUEROLL-TRIM- STITCH- C. WITH GSG- GAS
FRONT

NOV-23-'16

9036-. SHOE REPAIR OUTFIT. STYLE 31. G R O

COMBINATION FIN. & BUF. & SCOUR. WITH DOUBLE

BUF. ROLLS - TRIM - STITCH. C. WITH G. S. G. - GAS -

FRONT & R - 12 FE.

DEC - 23 - '16

9037-. PORTRAIT

MR. HENRY COTTRELL

DEC. 5 - '16

9038-. LASTING No. 6

FRONT & LEFT

Home Sec. Boots DEC 8 - '16

9039- LASTING MACH. No. 6- LM-

BACK + LEFT- LONG LEG BOOTS-

DEC-8-'16

9040- METALLIC HEEL + COUNTER

JACK- MOD. C-

MHJ

FRONT + RIGHT-

DEC-9-'16

9041- METALLIC HEEL + COUNTER

JACK- MOD. C-

MHJ

FRONT + LEFT-

DEC-9-'16

9042-OIL CANS

DEC-9-'16

9043-USMC- LASTING MACH.

No. 7- FRONT + LEFT-

LM

DEC-14-'16

9044-PREMIER HEEL PRICKING MACH.

FRONT + RIGHT- MON-B.

PHP

DEC-16-'16

9045 - PREMIER HEEL PRICKING MACH-
MOH-B. FRONT + LEFT.

DEC-16-'16

9046 - PREMIER HEEL PRICKING MACH-
MOH-B. BACK + RIGHT.

DEC-16-'16

9047 - CAMPBELL CYCLONE SEWING
FRONT + LEFT.

CC

DEC-21-'16

9048 - INSOLE TACKING MACH. No. 1.

FRONT + RIGHT

BL

DEC-22-'16

9049 - GOODY'S UPPER STAPLER

GRINDING MACH.

GUS.

DEC-26-'16

9050 - CAMPBELL LOCKSTITCH SEWING

MACH. BACK + LEFT - FOR SEWING

AUTO. TIRES-

DEC-28-'16

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

9051-. ECONOMY INSOLE CHANNELING

MACH. MOD. B.

ECM.

FRONT & LEFT.

JAN. 2-'17

9052-. BOSTON TACKING MACH.

FRONT & RIGHT.

BL

JAN. 4-'17

9053-. PYRAMID HEEL BUILDING

MATRICES FOR PATTERNS OF

HEEL JAWS.

JAN. 15-'17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

9054-PYRAMID HEEL BUILDING
MATRICES FOR PATTERNS OF
HEEL JAWS- JAN-15-'17

9055-PYRAMID HEEL BUILDING
METHOD OF PLACING MATRICES IN
RELATION TO HEEL & FINISHED PATTERNS.

9056-PYRAMID HEEL BUILDING
FINISHED PATTERNS & FINISHED
HEEL JAWS- JAN-15-'17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

9060-SECTIONAL FIRE-INSIDE

APPLICABLE TO FILING DESK.

JAN-18-'17

9061-ORCHIDS AT

WINSLOW GREEN-HOUSE

JAN-20-'17

9062-HAND ROUNDING CLAMPS.

MOB-R-

JAN-22-'17

9057- FILING DESK-

JAN-18-'17

9058- FILING DESK WITH COVER-

JAN-18-'17

9059- SECTIONAL FILE APPLICABLE
TO FILING DESK-

JAN-18-'17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

9063 - TWIX EDGE SETTING MACH-

FRONT & LEFT MOD. R-

RMES-

JAN-26-'17

9064 - GOODR'S CHANNEL LAYING MACH-

FRONT & RIGHT

GCL-

JAN-26-'17

9065 - COPY PHOTO OF

ORRELL ASHTON - INVENTOR.

JAN-26-'17

9066 - COPY PHOTO OF
FREDERIC ELI BERTRAND - INVENTOR -
JAN - 26 - '17

9067 - COPY PHOTO OF
LYMAN R. BLAKE INVENTOR
JAN - 26 - '17

9068 - COPY PHOTO OF
J. H. BUSSELL - INVENTOR -
JAN - 26 - '17

9069-. COPY PHOTO OF
FRANK CHASE - INVENTOR-

JAN-26-'17

9070-. COPY PHOTO OF
CHRISTIAN HANSEL - INVENTOR-

JAN-26-'17

9071-. COPY PHOTO OF
ALVIN HIGHTON ELLIOTT - INVENTOR-

JAN-26-'17

9072-. COPY PHOTO OF
ANDREW ESSLER- INVENTOR-

JAN-26-'17

9073-. COPY PHOTO OF
HARLEY P. FAIRCHILD- INVENTOR

JAN-26-'17

9074-. COPY PHOTO - OF
CHAS. W. GLESSON-

JAN- 26-'17

9075-COPY PHOTO OF
CHARLES GOODYEAR- INVENTOR-

JAN-26-'17

9076-COPY PHOTO OF
WILLIAM GORDON- INVENTOR-

JAN-26-'17

9077-COPY PHOTO OF
ELIAS HOWE - INVENTOR

JAN-26-17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

9078 - COPY PHOTO OF

STEPHEN Y. A. HUNTER - INVENTOR -

JAN - 26 - '17

9079 - COPY PHOTO OF

SHERMAN W. LADD - INVENTOR -

JAN - 26 - '17

9080 - COPY PHOTO OF

JAN E. MATZELIGER - INVENTOR -

JAN - 26 - '17

9081 - COPY PHOTO OF
GORDON MCKAY - INVENTOR -

JAN-26-'17

9082 - COPY PHOTO OF
JONATHAN MURPHY - INVENTOR

JAN-26-'17

9083 - COPY PHOTO - OF
FRED J. NASH - INVENTOR -

JAN-26-17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

9084 - COPY PHOTO OF
GEORGE L. ROLLINS - INVENTOR -

JAN-26-'17

9085 - COPY PHOTO OF
SIMON ROSS - INVENTOR -

JAN-26-'17

9086 - COPY PHOTO OF
ISAAC MERRITT SINGER -

JAN-26-'17

9087- COPY PHOTO OF

SETH DEXTER TRIPP- INVENTOR-

JAN-26-'17

9088- COPY PHOTO OF

CHARLES H. WILSON- INVENTOR-

JAN-26-'17

9089- COPY PHOTO OF

FREEMAN WINSLOW- INVENTOR-

JAN-26-'17

9090-ELLIOT ST. BEYERLY, TEAM. (GROUP)

INTER-OFFICE & FACTORY BOWLING

LEAGUE

JAN-30-'17

9091- SAME

JAN-30-'17

9092- GROUP. "THE RUNAWAYS"

CAST OF CHARACTERS.

FEB-2-'17

* 9093 - GROUP - "THE RUNAWAYS"

CAST OF CHARACTERS -

FEB - 2 - '17

9094 - GROUP - "THE RUNAWAYS"

CAST OF CHARACTERS -

FEB - 2 - '17

9095 - GROUP - "THE RUNAWAYS"

PRINCIPAL CHARACTERS -

FEB - 2 - '17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

* SEE OVER FOR NAMES.

9093 - FROM LEFT TO RIGHT STANDING -
Chas. Hutchinson - Sumner Bray - Milton Reid -
Edna Semple - Ben Altenheimer - Chris
Relihan -

FROM LEFT TO RIGHT SITTING -
MISS ALEXANDER - Frank Boston - Mrs. Connors
Ed Colhoun - Miss Marden -

9096-. PORTRAIT

MRS. ESTELLE CONTOURS.

FEB. 2-'17

9097-. PORTRAIT

MISS CARRIE MARNEY

FEB. 2-'17

9098-. PORTRAIT.

MISS ANNELE ALEXANDER.

FEB. 2-'17

9099-1. PORTRAIT

MISS ANELE ALEXANDER.

FEB. 2-'17

9500 - PORTRAIT

BEN ALTENHEIMER

FEB. 2-17

9501 - GR. OUTSOLE RAPID LOCKSTITCH - B - ROS
RIGHT - TAKEN FOR DRAWING ROOM

FEB. 9-17

9502 - COPY OF DRAWING

GR' OUTSOLE RAPID LOCKSTITCH

ROS

MOA - C -

FEB. 14-17

- 9503 - COPY OF DRAWING - EXPEDITE
FINISHING MACH. WIRING DIAGRAM
FOR ELECTRIC HEAT - XHF 2-15-'17
- 9504 - COPY OF DRAWING - GR. OUTSOLE
RAPID LOCKSTITCH. MOOLS. M70 - ORL -
WIRING DIAGRAM - 2-15-'17
- 9505 - COPY OF DRAWING - GR. OUTSOLE
RAPID LOCKSTITCH. MOM. A. ROS -
WIRING DIAGRAM - 2-15-'17

9506.-COPY OF DRAWING - GR' OUTSOLE
RAPID LOCKSTITCH - MONS. M+O. ORL
WIRING DIAGRAM - FEB. 15-'17

9507.-COPY OF DRAWING - GR' OUTSOLE
RAPID LOCKSTITCH - MONL - A. ROS -
WIRING DIAGRAM 2-15-'17

9508.-COPY OF DRAWING - GR' WELT + TURN
SHOE - MON. K - WTG
WIRING DIAGRAM - 2-15-'17

9509.- COPY OF DRAWING - GR' WELT & TURN
SHOE - MOD. K- WTC-
WIRING DIAGRAM- FEB. 15-'17

9510.- COPY OF PRINT FROM NEG. 9004.
GR. OUTSOLE RAPID LOCKSTITCH MOD. B- ROS
FEB. 14-'17

9511.- COPY OF PRINT FROM NEG. 9005
GR. OUTSOLE RAPID LOCKSTITCH MOD. C- ROS
FEB. 14-'17

9512 - COMMON SENSE SPLITTER

32" KNIFE

XXCSS.

FRONT + RIGHT

FEB. 19-'17

9513 - ECONOMY INSOLE CHANNELING

MOD. C - FRONT + LEFT

ECM -

MAR. 3-'17

9514 - UNIVERSAL DOUBLE CLINCH -

FRONT + RIGHT -

UDC

MAR. 3-'17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270
(FOR HEAD SEE E9441)

9515 - COPY - ORDER TO J. H. HUSTIS

RECEIVER B & M. R. R. Co. &c FROM W. C.

KENDALL - SUPT. TRANS. FEB. 17-17 - MAR. 12-'17

9516 - SAME, REVERSE SIDE OF SHEET -

DATED - FEB. 17-'17

MAR. 12-'17

9517 - COPY - ORDER TO J. H. HUSTIS, RECEIVER

OF B & M. R. R. Co. &c. FROM W. C. KENDALL

SUPT. TRANS. FEB. 19-'17

MAR. 12-'17

9518. RAPID STANDARD SCREW MACH.

FRONT + RIGHT (MOD-A) — R.S.

MAR-13-'17

9519 - U.S.M.C. UPPER CEMENTING

MOD. A. RIGHT SIDE

UCA

MAR. 23-'17

9520 - U.S.M.C. UPPER CEMENTING

MOD. A.

UCA

FRONT + RIGHT -

MAR. 23-'17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270.

9521 - LOUIS HEELE BREAST TRIMMING
MON. MARGARET RIGHT. RHB
~~DISCHARGE~~ 3-23-'17

9522 - LOUIS HEELE BREAST TRIMMING
MON. MARGARET LEFT RHB
~~DISCHARGE~~ 3-23-'17

9523 - PORTRAIT -
FRED CHURCHLEY APRIL - 4 - '17

9524-. PORTRAIT

WILFRED HALLINGS-

APRIL-4-'17

9525-. PORTRAIT

EDWARD STOTT

APR-4-'17

9526-. PORTRAIT

WILLIAM BLACK

APR-4-'17

9527- LOUIS HEEL BREAST TRIMMING
MOD-M- FRONT & RIGHT- RHB-
4-5-'17

9528- PORTRAIT-
EDWARD STOTT-
4-5-'17

9529- PORTRAIT-
EDWARD STOTT-
4-5-'17

9530- LOOSE NAILING MACH. No. 2

FRONT + RIGHT.

LN

APR-9-'17

9531- PLUMA SKIING MACH. MOD. E

FRONT + LEFT

PLU.

APR-13-'17

9532- PLUMA SKIING MACH. MOD. E

MACH. OPEN SHOWING BOTTOM. PLU-

APR-13-'17

9533 - PLUMA SKIYING MACH. MOD. E

OPEN - SHOWING BOTTOM - PLU

APR - 14 - '17

9534 - PLUMA SKIYING MACH. MOD. E - PLU

FRONT + LEFT WITH LEFT SIDE

OPEN -

APR - 14 - '17

9535 - ARRIVAL OF 5.20 P.M. TRAIN

FROM BOSTON - MAIN LINE

APR - 16 - '17

9536 - ARRIVAL OF 5.20 P.M. TRAIN
FROM BOSTON - MAIN LINE,
APR-16-'17

9537 - ARRIVAL OF 5.20 P.M. TRAIN
FROM BOSTON - MAIN LINE,
APR-16-'17

9538 - PLUMA SKIING MACH-
MOD - D - FRONT + LEFT PLU.
APR-18-'17

9539-. SHOE REPAIR OUTFIT- STYLE 32- G.R.O

STITCH. C. WITH ELEC. H. - COMBINATION FUR + BUF. +

SCOUR. WITH DOUBLE BUF. ROLLS - TRIM-

FRONT L - 1275

APR-24-'17

9540-. PLUMA SKIING - E

PLU

FRONT + L-

4-26-'17

9541-. SAME

PLU

LEFT SIDE - OPEN

For more information contact the Archives Center at archivescenter@si.edu or 202-633-0270

4-20-'17

9542 - PORTRAIT

MR. E. F. GRANNY

APR-27-'17

9543 - KNIFE WELT CUTTING

FRONT + LEFT

NO SYMBOL -

APR-27-'17

9544 - SAME

BACK + LEFT

NO SYMBOL -

APR-27-'17

9545-. MFG. MACH.

HEEL-SEAT BACKING-OFF

NO-4855- B1-30-

9546-. SAME

APR-30-'17

SHOWING A PORTION

APR-30-'17

9547-. MFG. MACH.

FORE-PART BACKING-OFF-

BACK & LEFT. NO. 3180-

APR-30-'17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

B1-30

9548 - MFG. MACH. FORE-PART BACKING-OFF

BACK + RIGHT

WITH DRIVING PULLEY

MAY-1-'17

9549 - SAME

BACK + RIGHT

WITHOUT DRIVING PULLEY

MAY-1-'17

9550 - COPY OF PRINT SHOWING A. D. ELLIOTT

INVENTOR IN WORK-SHOP. MAY-4-'17

9551--COPY OF PORTRAIT OF
ALVIN D. ELLIOTT-INVENTOR-

MAY. 4-'17

9552.-NAUMKEAG PAD DRYING MACH.-
FRONT + RIGHT-

MAY- 7-'17

9553.-NAUMKEAG PAD WETTING MACH
FRONT

MAY- 7-'17

9554. NAUMKEAG PAID WETTING MACH
FRONT- MAY-7-'17

9555. NAUMKEAG PAID WETTING MACH
FRONT + RIGHT- MAY-7-'17

9556. NAUMKEAG PAID WETTING MACH -
FRONT + RIGHT MAY-7-'17

9557-. NAUMKEAG PAD WETTING

FRONT + LEFT

MAY-7-'17

9558-. SHOE REPAIR OUTFIT - SPECIAL - FOR R.H. FIFE + C.

IN 3 SECTIONS - STITCHER END - LEFT - TWO STITCH-

ERS, C. ELEC. H. - DOUBLE UNIT BUFG + SCOUR, WITH

SINGLE BUFG. ROLL - FRONT - 3176. MAY-10-'17

9559-. SAME - MIDDLE SECTION - FRONT -

TRIMMER WITH PART OF DOUBLE UNIT FIN.

SECTION

For more information contact the Archives Center at archivescenter@si.edu or 202-887-3200

MAY-10-'17

9560-- SHOE REPAIR OUTFIT - SPECIAL 3176- MACH.

FOR R.H. FIFET CO. IN 3 SECTIONS -
ENGE-SETTING, SECT. RIGHT END -
DOUBLE UNIT FINISHING. - FRONT -

MAY-10-'17

9561-- MENTAL - W. ALCOCK

USMAA WHITES CHAMPION 1916

MAY-12-'17

9562-- FACTORY GIRL IN OVERALLS

MISS JOSEPHINE OGAFFY

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3370

MAY-17-'17

9563-FACTORY GIRL IN OVERALLS-

MISS JOSEPHINE OGDEN

MAY-17-'17

9564-SHOE REPAIR OUTFIT-18 FT. GRO

ELECTRIC HEAT + MOTOR DRIVE FOR

GEN. ELECTRIC CO-

MAY-19-'17

9565-EMBOSSING MACH-MOD-C. SHOWING

MOTOR

UE

MAY-26-'17

9566-.GR. INSOLE TOE SNIPPING MACH.
FRONT + RIGHT ITS

MAY-26-17

9567-.GR. WELT + TURN SHOE-(SEWING)
MACH. WITH GAS GENERATOR- W+T
BACK.

MAY-26-'17

9568-.USMC LASTING MACH. NO-6
FOR USE OF ENGRAVER L.M.

MAY-29-'17

9569 - E9821 - GOODY'S OUTSOLE
RAPID LOCKSTITCH - MOD. O - ORL -
MOTOR DRIVET - FRONT + R - 5-31-'17

9570 - E9822 - GOODY'S OUTSOLE
RAPID LOCKSTITCH - MOD. O - ORL
MOTOR DRIVET - FRONT + L - 5-31-'17

9571 - CAMPBELL LOCKSTITCH SEWING MACH -
WORK SUPPORT FOR CORNER SEWING CHS
6-4-'17

9572 - STITCHDOWN STAPLE LASTING -
MOD. D. FRONT + RIGHT - SSL -
JUNE 5-17

9573 - GR. EDGE SETTING + WHEELING
~~FRONT~~, FRONT + RIGHT ESW
JUNE 11-17

9574 - CONSOLIDATED HAND METHOD
LASTING HM
WELT SIDE LASTING 6-12-17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

9575- CLIMAX FINISHING SHAFT

MO. D. B.

6-13-17

9576- SHOE REPAIR OUTFIT TRUCK & TRAILER
FOR MASS. NATIONAL GUARD

FRONT & RIGHT VIEW 6-15-17

9577- SHOE REPAIR OUTFIT TRUCK & TRAILER
FOR MASS. NATIONAL GUARD.

REAR VIEW

6-15-17

9578-. SHOE REPAIR OUTFIT TRUCK & TRAILER
FOR MASS. NATIONAL GUARD

INTERIOR VIEW OF TRUCK 6-15-17

9579-. SHOE REPAIR OUTFIT TRUCK & TRAILER
FOR MASS. NATIONAL GUARD 6-15-17

INTERIOR VIEW OF TRAILER

9580-. GR. UNIVERSAL POUNDING & CHANNELING
MOD. E 6-20-17

UR & C

9581- BROCK HAND TACKER

FOR W.R. HURD 1ST

6-23-17

9582- CHAMPION STRIP BEVELING -

MOD-B. FRONT + RIGHT. CSB.

6-28-'17

9583- GR. UNIVERSAL ROUNDING AND

CHANNELING MACH. MOD-E URTC

FRONT + RIGHT

6-30-'17

9584-. EDGE SCOURING MACH

MO. A. FRONT + LEFT- E S A

JULY-7-17

9585-. REPAIR TRUCK- INTERIOR.

REAR + FRONT- OPERATOR-

JULY-20-17

9586-. REPAIR TRUCK- INTERIOR

REAR + FRONT

JULY-20-17

9587.-REPAIR TRUCK-INTERIOR
FRONT TO REAR-OPERATOR-

JULY-20-17

9588.-REPAIR TRUCK-INTERIOR.
FRONT TO REAR-

JULY-20-17

9589.-REPAIR TRUCK-
SIDE VIEW

JULY-20-17

9590-REPAIR TRUCK

BACK + LEFT

JULY-20-17

9591-REPAIR TRUCK

FRONT + RIGHT-WINDOWS OPEN

JULY-20-17

9592-REPAIR TRUCK

SHOWING STORAGE BATTERIES

JULY-20-17

9593.. REPAIR TRUCK - SHOWING
EMERGENCY KIT.

JULY 20-'17

9594.. REPAIR TRUCK - FRONT & RIGHT
WINDOWS OPEN.

NO TAG. J.L.H.

JULY 24-'17

9595.. MR. G. W. BROWN -
PORTRAIT

"HURRY UP" JOB

JULY 28-'17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

9596 - M^cKAY SEWING MACH. MSM

MOB-S - PORTION LOWER PART.

AUG - 8 - '17

9597 - DESK - MISS REBECCA JENNIE

EXP - DEPT.

AUG - 11 - '17

9598 - SAME

WITH FIGURE

AUG - 11 - '17

9599-. GROUP OF GIRLS ABOUT DESK
OF MISS REBECCA JENNIE
EXPERIMENTAL DEPT.

"BECKIE'S" LAST DAY-

AUG-11-1917

10100.-. FACTORY MAIL WAGON WITH
FIGURE - (LESTER STONE)

AUG-18-'17

10101.-. SAME

AUG-18-'17

10102.-. PORTRAIT -
W. H. TITUS

AUG-20-'17

10103-. PORTRAIT

W. H. TITUS-

AUG-20-'17

10104-. PORTRAIT

EDWIN M^C GILL

AUG-20-'17

10105-. PORTRAIT

EDWIN M^C GILL

AUG-20-'17

10106 - PORTRAIT

SAM CROSSLAND.

AUG. 20-17

10107 - PORTRAIT

SAM CROSSLAND

AUG. 20-17

10108 - PORTRAIT

HARVEY J. FERRIER

AUG. 22-17

10109 - PORTRAIT

HARVEY J. FERRIER -

AUG - 22 - '17

10110 - IMPROVED GEARLESS SOLE

CUTTING MACH. MOD. E. GSC

7 7/8 -

AUG - 21 - '17

10111 - IMPROVED GEARLESS SOLE

CUTTING MACH. MOD. B. GSC

3 7/8 -

AUG - 22 - '17

10112 - TOE SOFTENING MACH -
ELECTRIC HEAT ZTSM
MOH-7. AUG-22-'17

10113 - ROGERS - C. E
PORTRAIT -
AUG-24-'17

10114 - SAME
AUG-24-'17

10115 - PORTRAIT
JAMES M^c MAHON

AUG - 24 - '17

10116 - SAME

AUG - 24 - '17

10117 - PORTRAIT
F. A. COOK

AUG. 27 - 17

10118-1 PORTRAIT
F. A. COOK AUG. 27-17

10119-1 PORTRAIT AUG. 27-17
HARRY B. ELLIS

10120-1 PORTRAIT AUG. 27-17
HARRY B. ELLIS

10 121. GEARLESS SOLE CUTTER
M.D. J. GSC

AUG 27-17

10 122. PORTRAIT

W. R. HURD 2nd

AUG. 28-17

10 123. PORTRAIT

W. R. HURD 2nd

AUG. 30-17

10124-. PORTRAIT

W. R. HURD 2nd

AUG 30-17

10125-. SHOE DIE SAFETY FLANGE ZSD
(USMC-SOLE DIE)

SEPT-4-17

10126-. SHOE DIE SAFETY FLANGE
(USMC-SOLE DIE)

ZSD

SEPT-4-17

10127-1 SHOE DIE ZSD-
SAFETY FLANGE

(USMC-SOLE DIE) SEPT 4-17

10128-1 U.S.M.C. Lasting Mach.
No 7 LM

"Long Legged Boots" Sept 7-17

10129-U.S.M.C. LASTING MACH- LM-
No. 6. FOR LONG LEGGED BOOT

WORK- FRONT + RIGHT- SEPT-10-'17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

10130-. UNITS-

SEPT. 14-'17

10131-. IMPROVED GEARLESS SOLE
CUTTING MACH. MON. C- GSC
FRONT LEFT

SEPT. 17-'17

10132-. IMPROVED GEARLESS
SOLE CUTTING MACH. GSC
MON. H.

SEPT. 21-'17

10133 - LOOSE NAILING - MOD. B.

HEAD - FRONT -

NLN

SEPT. 28-'17

10134 - LOOSE NAILING - MOD. B.

NAIL - POTS + HORN -

NLN

FOR USE OF ENGRAVER.

SEPT. 28-'17

10135 - LOOSE NAILING - MOD. B.

HORN - FOR USE OF ENGRAVER.

NLN

SEPT. 28-'17

10136 - GR. WELT & TURN SHOE - MON - K - WTC

CENTER HEADS SHOWING DIFFERENCE

BET. STEAM HEAT ^{A1549+} & ELEC. HEAT ^{A2108+} OCT-5-'17

10137 - CENTENNIAL SPLITTING

MON - G. 14" BENCH - SMC

FRONT & RIGHT - OCT-6-'17

10138 - TAP & SOLE PRESS - MON - A

FRONT & LEFT - TSPA

OCT-8-'17

10139 - TAP & SOLE PRESS - MON - A -
SHOWING METHOD OF USE - TSPA
FRONT & LEFT OCT - 8 - '17

10140 - E6660 - IDEAL CLICKING
MACH - MON - C - ICM -
FRONT & RIGHT

10141 - LOOSE NAILING
MON - B - FRONT
OCT - 19 - '17

10142 - LOOSE NAILING NLN

MOD-B. FRONT & RIGHT-

OCT-19-'17

10143 - CENTENNIAL SPLITTING

MOD-G. 14" BENCH - FRONT - SMC

OCT-19-'17

10144 - LOOSE NAILING No. 2 LN

FITTED WITH AUTOMATIC JACK-

FRONT & LEFT

OCT-19-'17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

10145-TOE SOFTENING ZTSM

MOA-G. ELECTRIC HEAT-BENCH

OCT-22-'17

10146-E10231, LOOSE NAILING- NLTY

HORN MOA-B-

SEPT-12-'17

10147-E10232- LOOSE NAILING NLTY

HEAD-FRONT RIGHT

MOA-B-

SEPT-12-'17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

10148-.E10233-. LOOSE NAILING NLTN
HEAD-BACK+RIGHT MOA-B.
NAILING HORN SEPT-12-'17

10149-.E10234-. LOOSE NAILING NLTN
MOA-B. FRONT+RIGHT
SLUGGER HORN SEPT-12-'17

10150-.USMC- LAST PULLING ULP
MOA-A. FRONT+R-

OCT-24-'17

10151-. ECONOMY INSOLE REINFORCING
MACH-MON-B- 1R

FRONT + RIGHT- OCT-25-'17

10152-. SAME 1R

FRONT + LEFT

OCT-25-'17

10153-. REX PULLING QYER - MON-B-

FRONT + LEFT

OCT-26-'17

10154 - REX PULLING OVER MACH -
MON - E - NINE TACK PO
FRONT + LEFT NOV - 6 - 17

10155 - SAME PO
HEAD -
FRONT + LEFT NOV - 6 - 17

10156 - USMC. HEEL BREAST BEADING
MON - B - FRONT UHB
NOV - 7 - 17

10157 - USMC - HEEL BREAST BEADING
MON - B. - UHB

FRONT + LEFT - NOV - 7 - '17

10158 - PREMIER HEEL PRICKING PHP

MON - B. - TREADLE - FOR USE OF
ENGRAYER - NOV - 7 - '17

10159 - LOOSE NAILING MACH -

MON - B. - FRONT + R. - NLN
NOV - 2 - '17

10160 - USMC - EYELETTING

MOON - A.

TEM.

FRONT + RIGHT

NOV-5-'17

10161 - ANDIRONS AND TOTE BOX

NOV-13-'17

10162 - ANDIRONS WITH THREE BOXES
TIERED -

NOV-13-'17

10163 - HAND ELEVATING TRUCK
WITH AN IRONS & TOTE BOXES.

NOV-13-'17

10164 - STEEL BOXES FOR HAND OR
ELECTRIC ELEVATING TRUCK.

NOV-13-'17

10165 - HAND ELEVATING TRUCK
WITH LARGE STEEL BOX

NOV-13-'17

10166- ELEVATING-TRUCK-AND IRONS
LOADED WITH BAR STOCK

NOV-13-'17

10167- HAND ELEVATING TRUCK WITH
AND IRONS + LOAD-

NOV-13-'17

10168-

10169 - GR, TWIN SOLE MouldING
Мод-В - FRONT + LEFT - ATSM
Nov-13-'17

10170 - SAME
FRONT + RIGHT ATSM
Nov-13-'17

10171 - GR - JOINTING MACH.
Мод-П - WITHOUT GRINDER.
FRONT + RIGHT Nov-13-'17

10172 - GR. JOINTING MACH.

JM

MOO. B

FRONT + RIGHT

NOV. 14-'17

10174 - LOOSE NAILING MACH.

NLN

FITTED FOR HUNGARIAN WORK

FRONT + RIGHT.

NOV. 14-'17

10175 - GR. OUTSOLE RAPIA LOCKSTITCH

COPY OF PAGE IN CATALOGUE (OCT. 1904)

ROS-

DEC. 22-'17

10176 - GIR. FLEXIBLE SOLE MACH.

MOA-X

FXS

FRONT + RIGHT

NOV-15-'17

10177 - NAIL LOADING + DISTRIBUTING

ATTACHMENT - MOA-S -

NP

FRONT + RIGHT

NOV-15-'17

10178 - CHAMPION HEEL LIFT SKIVING

MOA-A

CLS

FRONT + RIGHT -

NOV-15-'17

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

10179-. ACME LEVELING MACH.

(WELT) FRONT + RIGHT- ACME

NOV-20-'17

10180-. TACKING + LAYING MACH.

GR. SOLE-

STL

FRONT

NOV-23-'17

10181-. SAME

FRONT + RIGHT

STL

NOV-23-'17

10182 - ANTIROTON FOR HAND
ELEVATING TRUCK.

NOV-27-'17

10183 - ANTIROTON FOR HAND
ELEVATING TRUCK.

NOV-28-'17

10184 - USMC - SERVICE FLAG
ON FACTORY.

NOV-30-'17

10185 - USMC. SERVICE FLAG
ON FACTORY - Broken -
NOV - 30 - '17

10186 - PYRAMID HILL BUILDING
MOPT. II. PARTIAL VIEW. PB
FRONT DEC - 1 - '17

10187 - SAME - PB
PARTIAL VIEW - BACK + RIGHT
DEC - 1 - '17

10188 - PYRAMIA HELL BUILDING PB.
МОН. П. PARTIAL VIEW.
BACK - DEC-1-'17

10189 - USMC. SERVICE FLAG -
COPY OF PRINT - (10184)

DEC-3-'17

10190 - PORTRAIT.
JOS. R. DRUGAN

DEC-5-'17

10191 - PORTRAIT

JOS. R. DRUGAN

DEC-5-'17

10192 - EDGE TRIMMING MACH. 7 PT

GRINDER - MOD. A - FITTED WITH TYPE

LOOMER CUTTER GRINDER ATTACH. 12-5-'17

10193 - SHOE DIE - SAFETY FLANGE ZSD.

DEC-6-'17

10194- E 10462 DUPLEX GROMMETT

AND WASHER MACH.

DE

FROM THE LEFT.

DEC-18-'17

10195- VERTICAL CAMERA

PHOTO. DEPT.

JAN-2-'18

10196- SAME

JAN-2-'18

10197-IMPROVED ANDIRON +
IRON BOX

JAN-3-'18

10198-IMPROVED ANDIRON WITH
IRON BOXES AS LOAD

JAN-3-'18

10199-IMPROVED ANDIRON WITH
LOAD SHORT BARS.

JAN-3-'18

MEMO.

REGULAR NEGATIVES 1 TO 1999 INCLUSIVE

"B" " 2000 TO 2199 "

REGULAR " 2200 TO 3099 "

"B" " 3100 TO 3499 "

NUMBERS TO BE USED FOR ANY PURPOSE

3500 TO 3999 INCLUSIVE

REGULAR NEGATIVES 4000 + UP

1 - NO NEGATIVE

2 - PSR - PLANET SOLE ROUNDING,
MACH.

3 - PSR

4 - PSR

5 - PSR

6 - PSR -

7 - RS - RAPID STANDARD SCREW MACH
HORNS + CENTERS

8 - RS

9 - RS.

10 - RS

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

11--RS

12--TNT- TAPER NAIL TACKING MACH.

13--TNT-

14--TNT-

15--TNT-

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

16 - TNT - TAPER NAIL TACKING MACH

17 - TNT

18 - SQ - SPATTER QUILTING MACH

19 - SQ

20 - LH - AMERICAN LIGHTNING
NAILING MACH

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

21 - LH

AMERICAN LIGHTNING MAILING MACH.

22 - LH

23 - LH

24 - LH

25 - LH

26 - No NEGATIVE

27 - L H - AMERICAN LIGHTNING NAILING
MACH

28 - WXS - WUNDERHOOKS MACH.

29 - WXS

30 - US - UNIVERSAL SLUGGING
MACH.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

31- US

UNIVERSAL SLUGGING MACH.

32- US

33- US

34- US

35- US

36 - VIEW NEGATIVE

37 - GOODYEAR WELT - W+T

38 - VIEW NEGATIVE

39. - W+T - WELT TURN SHOE MACH.

40. - W+T

41 - W + T - WELT + TURN SHOE MACH, GOODYEAR

42 - W + T

43 - W + T

44 - W + T

45 - L H

46. - ERM - VICTOR ROLLING MACH

47. - ERM

48. - ERM

49. - USS

50. - USS - GOODYEAR UNIVERSAL
SHANK SKIING MACH.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

51. - WSM - GOODYEAR WELT SPLITTING
MACH.

52. - ERM - VICTOR ROLLING MACH.

53. - HM - CONSOLIDATED HAND
METHOD LASTING MACH.

54. - HM

55. - HM

56. — HM- CONSOLIDATED HAND
METHOD LASTING MACHINE

57.- HM-

58.- HM-

59.- HM-

60.- VIEW NEG.

61 - VIEW NEG.

62 - URTC - GOODYEAR UNIVERSAL
ROUNDING + CHANNELING MACH.

63 - HM - HAND METHOD LASTING MACH -
CONSOLIDATED.

64 - HM

65 - HM

66-. H M.

67-. H M.

68-. VIEW NEG.

69-. H M.

70-. H M.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

71.- HM

72.- VIEW NEG-

73.- " .

74.- ПЧ COMP - AUTOMATIC HEEL
COMPRESSING MACH - MOD. ПЧ *4C

75.- ДЕ - DUPLEX FYPELETTING MACH



76 - □ E

77 - □ E

78 - □ E

79 - □ E

80 - #4 COMP

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

81-. 4 COMP -

82-. 4 COMP.

83-. 4 COMP

84-. 4 COMP

85-. SWS-GOODYEAR SHANK WELT
SKIING MACH.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

86 - SWS

87 - IC - GOODYEAR CHANNELING MACH
(FITTED FOR INSOLE & TURN WORK)

88 - HT - GOODYEAR HEEL TURNING
MACH.

89 - OC - GOODYEAR CHANNELING MACH.
(FITTED FOR OUTSOLE WORK)

90 - VIEW NEG-

91-. VIEW NEG-

92-. " "

93-. " "

94-. HT & FT - GOONYEAR HEEL TURNING &
GOONYEAR. FOREPART TURNING, MACHS

95-. VIEW NEG.

96-. VIEW NEG.

97-. TOE TIP PRESS

TTP.

98-. VIEW NEG.

99.- UNIVERSAL BOBBIN WINDER - UBW-

100-. "

"

"

"

"

101 - RAPID BOBBIN WINDER RBW

102 - " " " "

103 - UBW

UNIVERSAL BOBBIN WINDER - GOODYEAR -

104 - RBW

GOODYEAR RAPID BOBBIN WINDER -

105 - RBW

106 - ROS - GOODYEAR OUTSOLE RAPID
LOCK-STITCH MACH.

107 - WGTB - GOODYEAR WELT GROOVING +
BEYILING MACH.

108 - ROS

109 - ROS

110 - ROS

111 - RBW

112 - ROS

113 - ROS

114 - ROS

115 - ROS - DIAGRAM PIPING USED
WITH STEAM GENERATOR.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

116 - ROS - DIAGRAM PIPING TC

117 - ROS " " "

118 - ROS " " "

119 - ROS

120 - ROS

121 - ROS - GOODYEAR OUTSOLE RAPID
LOCK-STITCH MACH

122 - ROS

123 - TAMP + LINING CEMENTING MACH.
SLC

124 - " " " " " "
SLC

125 - WELT SHANK SKIVING
SWS

126 - GOODYR-INSOLE CHANNELING MACH
16

127 - " " " " "

128 - NEGATIVE BROKEN

129 - GUC- KNIVES

130 - GOODYR INSOLE CHANNELING MACH.
KNIVES

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

131 - GOODY'S INSOLE CHANNELING MACH
KNIVES IC

132 - " " " " "

133 - " " " " "

134 - " " " " "

135 - " " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

136 - FOOT POWER EYLETTING MACH. FPE

137 - GOODYR. ROTARY SOLE LAYING MACH.
GRSL

138 - " " " " "

139 - " " " " "

140 - " " " " "

141 - GOODYR, ROTARY SOLE LAYING MACH

142 - " " " " "

143 - " " " " "

144 - " " " " "

145 - " CHANNEL LAYING MACH CLW.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

146-. CHANNEL FLAP TURNING MACH

147-. " " " "

148-. " " " "

149-. POWER HEEL BREASTING " XXPBM

150.- PHB - IMPERIAL BREASTING MACH.
HEEL - MOD-B.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

296-. EXPEDITE

XHP

297-. NO NEGATIVE

298-. NAIL DISTRIBUTER MON-M.

ND.

299-. " " "

300-1 " " "

301-. NAIL DISTRIBUTER MoA-M- NA

302-. " " " "

303-. " " " "

304-. " " " "

305-. " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

306 - NAIL DISTRIBUTER MOD-M-NH

307 - " " " " "

308 - " " " " "

309 - FOREPART TRIMMER- F P T.
MOD-A.

310 - NO NEGATIVE

VIEWS

311 To 315. INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

291-. EXPEDITE

XHP

292-. "

"

293-. "

"

294-. "

"

295-. "

"

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

286 - VIEW NEG.

287 - XPENITE

XHF

288 - "

"

289 - "

"

290 - "

"

281 - TKG & RT

282 - SPRING HEEL TRIMMER SH T

283 - " " " "

284 - VIEW NEG

285 - " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

276 - Mc KAY KNIFE GRINDER

TKG

277 - " " " "

278 - " " " "

279 - " " " "

280 - TKG + RT

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

271-. RT

272-. "

273-. "

274-. "

275-. GUC. KNIVES
GOODYR UNIVERSAL CHANNELING,
MACH.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

266- . U I T

267- . "

268- . VIEW NEG

269- . RT - M^c KAY HEEL TRIMMING +
RAMPING MACH.

270- . RT " " "

261 - MIT

262 - "

263 - "

264 - "

265 - "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

256-. B+S - BEATING + SLASHING, GAYR-
NOV-14-1905

257-. "

258-. "

259-. VIEW NEG

260-. UIT - GOOFYEAR. UNIVERSAL
INSEAM TRIM. MACH.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

251 - VIEW NEG

252 - " "

253 - " "

254 - " "

255 - B & S

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

246- M^{rs} KAY COPELAND LASTING MACH
ML-

247- VIEW NEG.

248- " "

249- " "

250- " "

241.- M^cKAY COPFLAND LASTING MACH,
ML-

242.. " " " "

243-. " " " "

244-. " " " "

245-. " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

236. - M^cKAY COPELAND LASTING MACH. - ML-

237 - " " " "

238 - " " " "

239 - " " " "

240 - " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

231.- M^cKAY COPELAND LASTING MACH-ML-

232-- " " " "

233-- " " " "

234-- " " " "

235-- " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

226- M^cKAY COPELAND LASTING MACH
ML-

227- " " " " "

228- " " " " "

229- " " " " "

230- " " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

221-. VIEW NEG

222-. " "

223-. ХРЕДИТЕ ФИНИШИНГ МАШ. ХНФ

224-. " " " "

225-. " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

216- M^cKAY KNIFE GRINDING MACH

Nov-23-1904

217- " " " "

218- ROTARY EDGE-SETTING "

219- VIEW NEG

220- " "

211- M^cKAY HEEL TRIMMING MACH RT

212- " " " " "

213- " " " " "

214- " " " " "

215- " KNIFE GRINDING " TKG

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

206-. VIEW NEGATIVE

207-. " "

208-. " "

209-. " "

210-. " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

201-1. VIEW NEG

202-1 " "

203-1. GEM CEMENTER

GIC-

204-1. VIEW NEG.

205-1 " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

196- VIEW NEGATIVE

197- " "

198- " "

199- " "

200- " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

186 - NLN -

187 - GOODYR IMP. SELF LAYING MACH - ISL -

188 - ISL

189 - ISL

190 - NLN - HORNS + CENTERS

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

181 - RS - HORNS & CENTERS

182 - NLN

183 - "

184 - "

185 - "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

176.- REX POUNDING UP MACH 3-23-'01
NEW TREADLE ARRANGEMENT-PUM-

177-. " " " " "

178-. RS HORNS

179-. " "

180-. " HORN-CENTERS

171 - N2N

172 - "

173 - "

174 - "

175 - "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

166-. POM- 40°

167-. " "

168-. " "

169-. GUC- KNIVES -
GOODYR- UNIVERSAL CHANNELING MACH.

170-. NLY
LOOSE NAILING MACH.

For more information contact the Archives Center at archivescenter@slu.edu or 202-633-3270

161 - POM-40°

162 - " "

163 - " "

164 - " "

165 - " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270



156 - POM-40°

157 - " "

158 - " "

159 - " "

160 - " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

151 - PHB

152 - PHB

153 - PHB

154 - POM - 40°

155 - " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

316 - VIEW NEG.

317 - GOODY'S AUTOMATIC SOLE LEVELER.
GAL.

318 - " " " "

319 - " " " "

320 - " " " "

321 - GOODY'S AUTOMATIC SOLE LEVELER GAL

322 - " " " "

323 - " " " "

324 - " " " "

325 - " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

326 -	GOODYEAR	AUTOMATIC	SOLE	LEVELER	GAL
327 -	"	"	"	"	"
	TOE PIECES				
328 -	GOODYEAR	AUTOMATIC	SOLE	LEVELER	"
329 -	"	"	"	"	"
330 -	"	"	"	"	"

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

331.- GOODY'S AUTOMATIC SOLE LEVELER GAL

332 - " " " "

333 - " " " "

334 - " " " "

335.- HORNS FOR REGENT POWER STAMPER
RPS

For more information contact the Archives Center at archivescenter@sl.edu or 202-633-3270

VIEW

336 To 340 Inclusive

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

341 - VIEW NEG

342 - " "

343 - " "

344 - PLANET SOLAR ROUNDER

PSR.

345 - VIEW NEG.

346-. VIEW NEG

347-. SOLEY TAP ROUGHNER

STR

348-. " " " "

349-. " " " "

350-. " " " "

351 - SOLEY TAP ROUGHER STR

352 - " " " "

353 - VIEW NEG

354 - SOLEY TAP ROUGHER STR

355 - STITCH SEPARATOR - HADAWAY - HSS

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

356.- STITCH SEPARATOR HADAWAY. HSS

357-. " " " "

358-. " " " "

359-. VIEW NEG

360.- GOODY'S UNIVERSAL WELT BEATER UWB

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

361. - GOODYER-UNIVERSAL WELT BEATER UW B.

362. - NO NEGATIVE

363. - WI B - WELT INVENTING +
BURNISHING MACH. GOODYER.

364. - " " " "

365. - " " " "

364.- IMPROVED BABY SOLE CUTTING MACH. MOD. P
BPO

367- " " " " " " "

368- " " " " " " "

369- " " " " " " "

370- VIEW NEG

371-. VIEW NEG

372-. " "

373-. HEEL BREAST SCOURING MACH. HBS.

374-. " " " " HBS.

375. GEARLESS SOLE CUTTER- 27". GSC
MOO-A. - MISSING -

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

MISSING	376.	GEARLESS SOLE CUTTER- 2 FE.			GSC.
		MOA-A.			
	377-	"	"	"	"
	378-	"	"	"	"
	379-	"	"	"	"
380-	"	"	"	"	

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

381- ENSIGN LACING MACH

ELM.

382 -- " " " "

383 -- " " " "

384 -- " " " "

385-- " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

386.- ENSIGN LACING MACH.

ELM

387- " " " "

"

388- " " " "

"

389- " " " "

"

390.- GEARLESS SOLE CUTTER 3 FC.
MOD. B

GSC

-MISSING-

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

391. - GEARLESS SOLE CUTTER 3 FC. GSC
MOA-B -MISSING-

392 - " " " 4 FC " "
MOA-C

393 - " " " " "

394 - " " " " "

395 - " " " " "

396.- GEARLESS SOLE CUTTER 4 FC. GSC-
MOD. C.

397- " " " " "

398- INSOLE CHANNEL KNIVES IC

399- " " " "

400- " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

401.- VIEW NEG

402 - " "

403 - GEARLESS SOLE CUTTER - 5 FT. GSC
MOR, J

404 - " " " " "

405 - " " " " "

406.- GEARLESS SOLE CUTTER 5 Ft. GSC

MOB. J

407- " " " "

408- " " " "

409- " " 7 + 9 Ft " "

MOB.S. E + F

410- " " 7 Ft + 9 Ft. "

"

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

411. - GEARLESS SOLE CUTTER 9 FE. GSC
 MOD-F
- 412 -- " " " 7 & 9 FE. "
 MODS - E + F
- 413 -- " " " 7 FE. "
 MOD - E
- 414 -- VIEW NEG-
- 415 - INSOLE CHANNEL KNIVES IC

416. - INSOLE CHANNEL KNIVES - IC

417 - " " " "

418 - " " " "

419 - NO NEGATIVE

420 - TIP SCOURING MACH. MOD. G TTS

421. - TIP SCOURING MACH. MOD-G. TTS

422 - " " " " "

423 - " " " " "

424 - " " " " "

425 - VIEW NEG

426-. VIEW NEG

427-. " "

428-. NO NEGATIVE

429- REGENT STAMPING 1/4 SIZE
MONS. BYC- RPS

430 - " " " " " " " " " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

431-. RPS - MOD. C. 1/4
REGENT STAMPING MACHINE
432-- " " 1/4 " "
433-- " " 1/8 " "
434-- " " 1/8 " "
435-- " " 1/8 " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

436 - RPS - MOD-C. 7/8

REGENT STAMPING MACH.

437 - " " 1/8 " "

438 - " " 1/10 " "

439 - " " 1/16 " "

440 - VIEW NEG

VIEW

441 To 450. INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

451 - VIEW NEG

452 - " "

453 - " "

454 - " "

455 - COMPRESSED LADIES HEELS

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

VIEWS

456 To 480 INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

486 - IMPROVED SOLE LAYER

ISL.

487 -

"

"

"

488 -

"

"

"

489 -

"

"

"

490 -

"

"

"

For more information contact the Archives Center at archivescenter@slu.edu or 202-633-3270

491-IMPROVED SOLE LAYER

ISL-

492- " " " "

493- " " " "

494- VIEW NEG

495- " "

VIEWS

496 To 500 INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270.

501-. POWER HEEL BREASTING MACH $\frac{1}{8}$
- XX PBM

502-. VIEW NEG.

503-. " "

504-. " "

505-. POWER HEEL BREASTING MACH $\frac{1}{8}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

VIEWS

506 To 515 Inclusive

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

516-. VIEW NEG.

517-. " "

518-. " "

519.- EROS-RAND MARKING MACH.
1/4

520-. " " " "
1/8

VIEWS

521 To 525 Inclusive

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

526-. VIEW NEG.

527- LIGHTNING ~~HEELER~~ - 1/2 SIZE LH
NAILER. AMERICAN -

528-. VIEW NEG.

529-. " "

530-. " "

531 - SUMMIT SPLITTING MACH. 18" SSF
1/6

532 - " " " " " "
1/6

533 - " " " " " "
1/8

534 - " " " " " "
1/8

535 - " " " " " "
1/12

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

536.- SUMMIT SPLITTING MACH. 18"
 $\frac{1}{12}$ SSE

537-. VIEW NEG

538-. " "

539-. " "

540-. " "

541-	COMMON SEAM RUBBER				CSR-
	$\frac{1}{8}$				
542-	"	"	"	"	"
	$\frac{1}{8}$				
543-	BOSTON LASTING MACH.				BL-
	$\frac{1}{4}$				
544-	"	"	"	"	"
	$\frac{1}{4}$				
545-	"	"	"	"	"
	$\frac{1}{6}$				

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

546 - BOSTON LASTING MACH-

$\frac{1}{6}$

547 - " " "

$\frac{1}{6}$

548 - " " "

$\frac{1}{8}$

549 - " " "

$\frac{1}{8}$

550 - " " "

$\frac{1}{8}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

551-. APEX CHANNELING MACH ACM.
MON-C- $\frac{1}{4}$

552-. $\frac{1}{4}$ " " " "

553-. $\frac{1}{6}$ " " " "

554-. $\frac{1}{6}$ " " " "

555-. $\frac{1}{6}$ " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

556-. APEX CHANNELING MACH- ACM.
MOD-C- $\frac{1}{6}$

557-. $\frac{1}{8}$ " " " "

558-. " " " "
 $\frac{1}{8}$

559-. " " " "
 $\frac{1}{12}$

560-. VIEW NEG

561-. VIEW NEG

562- " "

563- " "

564- " "

565-. POUNDING UP MACH.

PUM.

- 566- POUNDING UP MACH
GAS HEATING DEVICE PUM
- 567- " " "
STEAM HEATING DEVICE "
- 568- " " "
ALCOHOL HEATING DEVICE "
- 569- " " "
TOP VIEW "
- 570- VIEW NEG

571-. VIEW NEG.

572-. " "

573-. POUNDING UP MACH.

PUM

574-. VIEW NEG.

575-. HEEL PLATE NIES

VIEWS

576 To 585 INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

586- SUMMIT SPLITTING MACH 7 1/2" SSE
1/6

587- " " " " "
1/6

588- " " " " "
1/8

589- " " " " "
1/8

590- " " " " "
1/8

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

591.- SUMMIT SPLITTING MACH. $7\frac{1}{2}$ " SSF
 $\frac{1}{8}$

592.- $\frac{1}{12}$ " " " " "

593.- NO NEGATIVE

594.- VIEW NEG-

595.- " "

VIEWS

596 To 600 INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

601.- CHANNEL OPENING MACH-MOR, B. CFT

$\frac{1}{4}$

602-- $\frac{1}{4}$ " " " " " "

603-- $\frac{1}{6}$ " " " " " "

604-- $\frac{1}{8}$ " " " " " "

605-- $\frac{1}{8}$ " " " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

- 606 - HANA ROUNDING CLAMP ARC-
 $\frac{1}{8}$
- 607 - CEMENT POT - ROSS TYPE CP
 $\frac{1}{8}$ - 1 1/2 pts
- 608 - " " " "
 $\frac{1}{8}$ - 1 GAL -
- 609 - " " " "
 $\frac{1}{8}$ - 1/2 GAL -
- 610 - CRISPITY JACK PARTS CLJ
 $\frac{1}{8}$ -

611-. CRISPIN JACK PARTS

CLJ

$\frac{1}{8}$

612-. CEMENT POTS

OLA STYLE - $\frac{1}{2}$ TIGAL - $\frac{1}{8}$ SIZE

613-. BLOCK PLANE + HEEL BUILDING BLOCK-

$\frac{1}{8}$

614-. VAMP POLISHING MACH

VP

$\frac{1}{8}$

615-. APEX TAP SKIVING OR RAMP SPLITTING
MACH. MOD. A - $\frac{1}{6}$ SIZE

616 - APEX TAP SKIVING MACH - MOD - A T+RS
 $\frac{1}{4}$

617 - $\frac{1}{4}$ " " " " " "

618 - $\frac{1}{6}$ " " + SOFT-ROUNDING MACH. T.R.

619 - $\frac{1}{6}$ " " " " " "

620 - $\frac{1}{6}$ " " " " " "

621.- Apex Tap & Sole Rounding Mach. TR.

$\frac{1}{6}$
622.- ~~BOSTON~~ TACKING MACH $\frac{1}{6}$ BL

623.- Mc. Kay Insole Flexing Mach. MOD-R-
 $\frac{1}{8}$ MIF

624.- $\frac{1}{8}$ " " " " " "

625.- Button Fly Sealing Mach. MOD. S.
 $\frac{1}{5}$ BFFS.

626. BUTTON FLY SCOLLORING MACH. MON-S -
 $\frac{1}{8}$ BFSS

627. POST HEEL BREASTING MACH. POST-HB
 $\frac{1}{8}$

628. " " " " " " "
 $\frac{1}{8}$

629. VIEW NEG

630. " "

631 - POST HEEL BREASTING MACH POST-HB
 $\frac{1}{6}$

632 - EM - EMBOSSEING MACH. MOD. R.
 $\frac{1}{8}$

633 - EM -
 $\frac{1}{6}$

634 - BOTTOM STAMPING MACH. MOD. R. BSM
 $\frac{1}{8}$

635 - $\frac{1}{8}$ " " " " BSM

636.-IPS- IMPROVED PATTERN SHEARS, MOD-R
1/8

637.- IPS - 1/4 SIZE

638.- VIEW NEG

639.- HАND МЕТНОП LASTING MACH. HM.

640.- COMMON FOOT POWER PUNCH. MOD-A
FPP.

641-. VIEW NEG

642-. " "

643-. BOSTON TACKING MACH. $\frac{1}{16}$

644-. UCR - UPPER CLEANING MACH
 $\frac{1}{8}$

645-. VIEW NEG

646-. UCR- UPPER CLEANING MACH.
 $\frac{1}{8}$

647-. " " " "
 $\frac{1}{8}$

648-. VIEW NEG.

649-. FSR- Finishing SHAFT MOR-R.

650-. VIEW NEG.

651. - PULLING-OVER MACH. ARM SHOWING,
ATTACHMENT. PO - $\frac{1}{4}$
652. - FSR - FINISHING SHAFT MON-R. FSR -
 $\frac{1}{8}$
653. - GOONER LIP TURNER HLT
 $\frac{1}{6}$
654. - " " " " "
 $\frac{1}{4}$
655. - " " " " "
 $\frac{1}{6}$

656-. VIEW NEG

657-. BRIGGS E. WELT + TURRY MACH - GR - W + T - 1

658.-	$\frac{1}{6}$	"	"	"	"
659.-	$\frac{1}{4}$	"	"	"	"
660.-	$\frac{1}{6}$	"	"	"	"
	$\frac{1}{4}$	"	"	"	"

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

661-. BRIGGS E - WELT + TURRY MACH, GR-WY-T-L

$\frac{1}{4}$

662-- $\frac{1}{4}$ " " " " "

663-- $\frac{1}{4}$ " " " " "

664-- $\frac{1}{4}$ " " " " "

665-- $\frac{1}{4}$ " " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

666. — BRIGGS F. WELTY TURN MACH. GR. WY T-E
 $\frac{1}{4}$

667. — $\frac{1}{4}$ " " "

668. — $\frac{1}{6}$ " " "

669. — $\frac{1}{6}$ " " "

670. — $\frac{1}{6}$ " " "

671.- BRIGGS E. WELTY TURN GR-W + T-E
 $\frac{1}{6}$ COUNTER SHAFT PARTS

672.- BRIGGS E WELTY TURN MACH. GR-W + T-E
 $\frac{1}{8}$

673.- VIEW NEG.

674.- VULCAN FOOT POWER EYELETTING MACH
 $\frac{1}{6}$ FPE

675.- " " " "

676-	VULCAN FOOT POWER KEYLETING MACH	
$\frac{1}{6}$		FPE
677-	TAP CUTTING MACH.	CAM
$\frac{1}{6}$		
678-	" " "	"
$\frac{1}{6}$		
679-	VIEW NEG.	
680-	" "	

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

681-	INSOLE CHANNEL MACH				
	$\frac{1}{4}$ ECONOMY-				ECM-
682-	VULCAN FOOT POWER EYELETTING MACH.				
	$\frac{1}{4}$				FPE
683-	"	"	"	"	"
	$\frac{1}{4}$				
684-	"	"	"	"	"
	$\frac{1}{4}$				
685-	"	"	"	"	"
	$\frac{1}{8}$				

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

686. - JUPITER FOOT POWER LYLETING MACH-
 $\frac{1}{6}$ FPF

687. - GILMORE BUFFER - MOD. G GB
 $\frac{1}{4}$

688. - " " " "
 $\frac{1}{4}$

689. - " " " "
 $\frac{1}{8}$

690. - " " " "
 $\frac{1}{12}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

691- GILMORE BUFFER GB.
 $\frac{1}{12}$

692- " " "
 $\frac{1}{6}$

693- VIEW NEG.

694- GILMORE BUFFER GB
 $\frac{1}{12}$

695- " " "
 $\frac{1}{12}$

696-. VIEW NEG.

697-. " "

698-. NO NEGATIVE

699-. HERCULES LEVELER H L
 $\frac{1}{4}$

700-. " " " "
 $\frac{1}{6}$ Mar-29-1907

701.- HERCULES LEVELER -

H. L.-

$\frac{1}{6}$

702.-

$\frac{1}{6}$

"

"

"

703.-

$\frac{1}{6}$

"

"

"

704.-

$\frac{1}{4}$

"

"

"

705.-

$\frac{1}{6}$

"

"

"

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

706- HERCULES LEVELER - H.L.
 $\frac{1}{8}$

707- " " "
 $\frac{1}{12}$

708- " " "
 $\frac{1}{12}$

709- " " "
 $\frac{1}{12}$

710- " " "
 $\frac{1}{12}$

- 711 - HERCULES LEVELER HL
 $\frac{1}{12}$
- 712 - " " " "
 $\frac{1}{8}$
- 713 - GAYR WELT INVENTING + BURNISHING
 MACH - $\frac{1}{8}$ WIB
- 714 - " " " " "
 $\frac{1}{6}$
- 715 - " " " " "
 $\frac{1}{6}$

721-. VIEW NEG

722-. " "

723-. " "

724-. STAPLE FASTENER $\frac{1}{6}$ SF

725-. " " $\frac{1}{4}$ "

726-. STAPLE FASTENER SF
 $\frac{1}{4}$

727-. " " "
 $\frac{1}{2}$

728-. HERCULES LEVELER HL
 $\frac{1}{6}$

729-. STAPLE FASTENER SF
 $\frac{1}{4}$

730-. STAPLE FASTENER "
 $\frac{1}{8}$

731-	STAPLE FASTENER -		SF
	$\frac{1}{6}$		
732-	"	"	WRENCHES
			"
733-	"	"	"
	$\frac{1}{6}$		
734-	"	"	"
	$\frac{1}{6}$		
735-	"	"	"
	$\frac{1}{4}$		

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

736 - STAPLE FASTENER
 $\frac{1}{4}$

SF

737 - VIEW NEG

738 - " "

739 - STAPLE FASTENER
 $\frac{1}{2}$

SF

740 - NO NEGATIVE

741-¹/₄ APEX CHANNELER MOD-C - ACM-

742-¹/₄ " " MOD-B - ^{CFT}~~ASCB~~

743-¹/₄ ACC " MOD-C
APEX CHANNEL OPENING MACH.

744-¹/₄ CFT MOD-B
CHANNEL OPENING MACH. APEX

745-¹/₄ ACC MOD-C
APEX CHANNEL OPENING MACH

746-- Acc- MoA-C

$\frac{1}{4}$

747-- " "

$\frac{1}{6}$

748-- CFT " B

$\frac{1}{6}$

749-- Acc " C

$\frac{1}{8}$

750-- CFT " B

$\frac{1}{8}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

VIEWS.

751 To 755 INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

756-1 NO NEGATIVE

757-1 VIEW NEG.

758-1 CFT- $\frac{1}{4}$

CHANNEL OPENING MACH. MON-B

759-1 " $\frac{1}{8}$

760-1 " $\frac{1}{4}$

761- TE - FE - FGM

FOR ALL THREE MACHINES - $\frac{1}{6}$ SIZE.

762- THIN EDGE MACH. MOD-A $\frac{1}{6}$ TE

763- FEATHER EDGE MACH. MOD-A. $\frac{1}{6}$ FE

764- THIN EDGE MACH. MOD-A. $\frac{1}{6}$ - TE

765- FE MOD.A. $\frac{1}{6}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

766-- TE- $\frac{1}{4}$

767-- TE $\frac{1}{4}$

768-- TE $\frac{1}{4}$

769-- FE- $\frac{1}{4}$

770-- FGM- MOD-A. $\frac{1}{4}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

771-.FGM- MOD.A. $\frac{1}{6}$

772-.TF- MOD-A. $\frac{1}{4}$

773-.TF- MOD. A. $\frac{1}{4}$

774-.FGM- MOD. A. $\frac{1}{4}$

775-.BLOCK PLANE $\frac{1}{6}$

776-- FGM - MOM - A. $\frac{1}{4}$

777-- TE KNIVES - FULL SIZE

778-- FGM - KNIVES

779-- FE KNIVES

780-- VIEW NEG

VIEWS

781 To 785 INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

786-- VIEW NEG

787-- UR+C- 1/4

788-- " "

789-- " "

790-- " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

791-. U R T C - $\frac{1}{4}$

792-. " " $\frac{1}{4}$

793-. " " $\frac{1}{4}$

794-. " " $\frac{1}{4}$

795-. " " $\frac{1}{4}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

796-. URTC- $\frac{1}{2}$

797-. WELT GROOYER + BEVELER-KNIVES
 $\frac{1}{2}$ WG+B

798-. " " " " "
 $\frac{1}{2}$

799-. " " " " "
FULL SIZE.

800-. WELT GROOYER + BEVELER - PARTS
FULL SIZE.

801- WELT GROOVERT BEVELER - $\frac{1}{4}$

WG+B

802- " " " " $\frac{1}{4}$

803- " " " " $\frac{1}{6}$

804- " " " " $\frac{1}{6}$

805- URTC $\frac{1}{6}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

806-. URTC- $\frac{1}{8}$

807-. SMR- $\frac{1}{6}$

808-. " $\frac{1}{6}$

809-. " $\frac{1}{6}$

810-. " $\frac{1}{8}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

811-. SMR- $\frac{1}{6}$

812-. " $\frac{1}{6}$

813-. " $\frac{1}{6}$

814-. HEEL SCOURING MACH. MOA-R-
SMR- $\frac{1}{4}$

815-. HEEL SCOURING MOA-R- SMR-
 $\frac{1}{3}$

VIEWS

816 To 820 INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

821-. VIEW NEG.

822-. ROTARY HEEL BREASTING, MACH $\frac{1}{12}$
RHB

823-. " " " " "
RHB $\frac{1}{6}$

824.- SUMMIT SPLITTING, MACH $7\frac{1}{2}$ " $\frac{1}{8}$
SSF

825-. ROTARY HEEL BREASTING, MACH $\frac{1}{6}$
RHB

826.- ROTARY HEEL BREASTING MACH. $\frac{1}{6}$

RHB

827- " " " " $\frac{1}{6}$

828- " " " " $\frac{1}{6}$

829- " " " " $\frac{1}{4}$

830- " " " " $\frac{1}{4}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

831-	ROTARY HEEL BREASTING MACH.	$\frac{1}{8}$
		RHB
832-	" " " " "	" " $\frac{1}{8}$
833-	" " " " "	" " $\frac{1}{6}$
834-	HEEL SEAT ROUGH ROUNDER	$\frac{1}{6}$
		HSRA
835-	" " " " "	$\frac{1}{6}$
		HSRR.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

836.- HEEL SEAT ROUGH ROUNDER $\frac{1}{8}$ HSRR.

837- " " " " $\frac{1}{8}$ "

838- " " " " $\frac{1}{8}$ "

839- " " " " $\frac{1}{8}$ "

840- VIEW NEG-

841 - SUMMIT SPLITTER 28" $\frac{1}{2}$ 28" SS

842 - " " " $\frac{1}{2}$ "

843 - " " " $\frac{1}{2}$ "

844 - " " " $\frac{1}{8}$ "

845 - " " " $\frac{1}{8}$ "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

846 - SUMMIT SPLITTER - 28" - $\frac{1}{6}$ 28" SS

847 - " " " " $\frac{1}{4}$

848 - " " " " $\frac{1}{12}$

849 - " " " " $\frac{1}{12}$

850 - " " " " $\frac{1}{12}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

851 - SUMMIT SPLITTER. 28" - 1/8

852 - " " " " 1/8

853 - VIEW NEG.

854 - VIEW NEG.

855 - VIEW NEG.

856-. VIEW NEG.

857-. ATLAS LEVELER $\frac{1}{6}$ AL

858-. " " $\frac{1}{6}$ "

859-. " " $\frac{1}{6}$ "

860-. " " $\frac{1}{6}$ "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

861- ATLAS LEVELER $\frac{1}{6}$

862- " " $\frac{1}{6}$

863- " " $\frac{1}{6}$

864- " " $\frac{1}{6}$

865- " " $\frac{1}{8}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

866- ATLAS LEVELER - $\frac{1}{8}$

867- " " " $\frac{1}{8}$

868- " " " $\frac{1}{8}$

869- " " " $\frac{1}{8}$

870- " " " $\frac{1}{8}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

871-. ATLAS LEVELER- $\frac{1}{8}$

872.. " " $\frac{1}{8}$

873.. " " $\frac{1}{8}$

874.. " " $\frac{1}{8}$

875.. " " $\frac{1}{8}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

876 - ATLAS LEVELER - $\frac{1}{8}$

877 - " " $\frac{1}{4}$

878 - " " $\frac{1}{4}$

879 - " " $\frac{1}{4}$

880 - " " $\frac{1}{4}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

881- ATLAS LEVELER. $\frac{1}{4}$

882- " " $\frac{1}{4}$

883- " " $\frac{1}{12}$

884- " " $\frac{1}{12}$

885- " " $\frac{1}{12}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

886-. ATLAS LEVELER - $\frac{1}{12}$

887-. SPRING HEEL TRIMMER - $\frac{1}{12}$ SHT.

888-. SHT - $\frac{1}{8}$ "

889-. SHT - $\frac{1}{8}$ "

890-. SHT - $\frac{1}{8}$ "

891-. SPRING HEEL TRIMMER $\frac{1}{8}$

892 -- " " " " $\frac{1}{4}$

893 -- VIEW NEG

894.- SPRING HEEL TRIMMER- $\frac{1}{2}$

895-. VIEW NEG-

VIEWS

896 To 905 INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

906-. VIEW NEG

907-. APEX FLESHING OR RAMPING MACH
MOD-B - $\frac{1}{8}$ - HFGM

908-. APEX FEATHER EDGE + SHANK REDUCING
MACH MOD-B - $\frac{1}{8}$ HFE

909-. HFGM - $\frac{1}{4}$

910-. HFE - $\frac{1}{4}$

911-. HSHT - 1/4

912- TR BUSHINGS FOR HFE-HFGM- HSHT

913-. HFGM - 1/6

914-. HFE - 1/6

915-, HSHT - 1/6

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

916-. VIEW NEG.

917-. HFE $\frac{1}{8}$

918-. HFGM- $\frac{1}{8}$

919-. HSH T- $\frac{1}{8}$

920-. HFE- $\frac{1}{8}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

921.- HEEL BREASTING MACH MOD.W.

W + H H B - $\frac{1}{6}$

922-. W + H H B - $\frac{1}{8}$

923-. " "

924-. POWER GUMMING MACH PGM-

$\frac{1}{8}$ -

925-. $\frac{1}{8}$ " " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

926-. PGM- $\frac{1}{6}$

927-. " $\frac{1}{6}$

928-. " $\frac{1}{4}$

929-. STAR LEVELER- $\frac{1}{20}$
MOH-S- SLM-

930-. " " $\frac{1}{20}$
MOH-S- SLM.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

931-. SLM- $\frac{1}{8}$

932-. NO NEGATIVE

933-. SLM- $\frac{1}{8}$

934-. NO NEGATIVE

935-. RPM- $\frac{1}{6}$

ROYAL PERFORATING MACH. MOD. A

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

936-. RPM- $\frac{1}{6}$

937-. " $\frac{1}{8}$

938-. " $\frac{1}{8}$

939-. " $\frac{1}{4}$

940-. " $\frac{1}{4}$

941 " $\frac{1}{2}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

VIEWS

942 TO 955 INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

956.- STRAIGHT EDGE FOLDER SFF

957.- LOOSE NAILER $\frac{1}{8}$ NLN

958.- " " $\frac{1}{8}$ "

959.- " " $\frac{1}{6}$ "

960.- " " $\frac{1}{6}$ "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

961- LOOSE NAILER - $\frac{1}{4}$ NLN

962- " " $\frac{1}{12}$ "

963- HEEL COMPRESSOR No. 4- $\frac{1}{8}$ #4C

964- " " " $\frac{1}{8}$ "

965- " " " $\frac{1}{8}$ "

966-. HEEL COMPRESSOR No. 4- $\frac{1}{8}$ #4C

967-. NO. NEGATIVE

968-. HEEL COMPRESSOR- No 4 - $\frac{1}{8}$ "

969-. " " " " $\frac{1}{8}$ "

970-. " " " " $\frac{1}{8}$ "

971-HEEL COMPRESSOR No 4- $\frac{1}{8}$ #4C

972- " " " " $\frac{1}{6}$ "

973- " " " " $\frac{1}{6}$ "

974- " " " " $\frac{1}{4}$ "

975- " " " " $\frac{1}{20}$ "

976-HEEL COMPRESSOR No. 4- $\frac{1}{20}$ #4C

977- " " " " $\frac{1}{20}$ "

978- " " " " $\frac{1}{20}$ "

979- GOODYEAR Moulding Mach. $\frac{1}{4}$

980- " " " " $\frac{1}{8}$
TSM
TSM

981-	REX	POUNDING	UP	MACH.	$\frac{1}{8}$
					PUM.
982-	"	"	"	"	$\frac{1}{8}$
983-	"	"	"	"	$\frac{1}{8}$
984-	"	"	"	"	$\frac{1}{6}$
985-	"	"	"	"	$\frac{1}{6}$

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

986-. REX POUNDING UP MACH. PUM $\frac{1}{6}$

987-. " " " " " " $\frac{1}{4}$

988-. " " " " " " $\frac{1}{20}$

989-. KNURLING MACH KM- $\frac{1}{6}$

990-. " " " " $\frac{1}{8}$

991-. KNURLING MACH. KM- $\frac{1}{8}$

992-. NO. NEGATIVE

993-. HEEL BREAST SCOURING MACH. $\frac{1}{12}$
MOD. N. THBS

994-. " " " " " " $\frac{1}{8}$
THBS.

995-. VIEW NEG.

VIEWS.

996 To 1005 INCLUSIVE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

1051.- EDGE SETTING DEVICE FOR WOOD
HEELS ON RMES. $\frac{1}{8}$

1052 -- VIEW NEG.

1053 -- VIEW NEG.

RMES

1054 -- " "

1055 -- " "

1081 - CROWN TIP PUNCHING MACH $\frac{1}{12}$
MOP-P TTP

1082 - VIEW NEG.

1083 - WUNDERHOOK MACH. WXS

1084 - PUM. 4x5 OLD PLATES

1085 - VIEW NEG.

1091-- VIEW NEG

1092-- PIPING FOR BRIGGS TENSION

1093-- NEW POWER HAMMER - MOD-B. $\frac{1}{6}$
June-3-1908 PH.

1094-- SINGLE SOLE Moulding MACH.
MOD-S - $\frac{1}{20}$ SPSM.

1095-- " " " " " " $\frac{1}{20}$
SPSM.

1206. AMERICAN MOUNTING ATTACHMENT
OLD NEG.

1207. VIEW NEG.

1208. " "

1209. " "

1210. HLC - $\frac{1}{16}$

HUB LINING CEMENTING MACH.

MOA-F

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

1501-. VIEW NEG

1502-. GOODYEAR-WELT + TURN SHOE MACH.
W + T. Full V.

1503-. " " " " " " $\frac{1}{2}$

1504-. " " " " " " $\frac{1}{3}$

1505-. " " " " " " $\frac{1}{3}$

1811-. VIEW NEG.

1812-. " "

1813-. " "

1814-. " "

1815-. DUPLEX DYLTTING MACH. DE
FULL SIZE

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

1881-1 STAPLE FASTENING MACH. MOD. II - $\frac{1}{12}$
SF

1882-1 VIEW NEG-

1883-1 NAYY PEGGING MACH. PEG CUTTING
HORN MECHANISM IP

1884-1 VIEW NEG

1885-1 GOODYEAR INSOLE CHANNELING
MACH. KNIVES IC

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

VIEWS

1901 TO 1999 INCLUSIVE

NUMBERS FROM 2000 TO 2199 INCLUSIVE

TO BE USED AS "B" NUMBERS, OR FOR

BOX FACTORY NEGATIVES-

THE "B" NUMBERS FORM ANOTHER PART

FOR MORE INFORMATION CONTACT THE ARCHIVES CENTER AT archivescenter@si.edu OR 202-633-3270
OF THIS CARD CATALOGUE

2305-. VIEW NEG

2306-. " "

2307-. " "

2308-. TIP DESIGN FOR PAT. DEPT- 5-10

2309-. VIEW NEG

23701 - ROSS-MOYER CORRUGATED RUBBER
FINISHING SHAFT WHEEL

2371 - ROSS-MOYER - CORRUGATED FIN. SHAFT ROLL

2372 - ROSS-MOYER - COR. RUBBER FIN. SHAFT
WHEEL

2373 - ROSS-MOYER. TOP PIECE SCOURING WHEEL

2374 - ROSS-MOYER - COR. RUBBER SPRING-HEEL
FINISHING WHEEL.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

Deposited by Mrs. J. Ross

2375- ROSS-MOYER-CORRUGATED RUBBER
HEEL BREAST FIN-WHEEL (Sent to Boston office)

2376- VIEW NEG.

2377- HANNDY HEEL PRESS- $\frac{1}{4}$ HHP

2378- " " " $\frac{1}{10}$ "

2379- " " " $\frac{1}{20}$ "

2555-. NO NEGATIVE

2556-. NO NEGATIVE

2557-. NO NEGATIVE

2558-. LANNIS + PEARSON MACHINES
FOR JUNK- GI-

2559-. VIEW NEG.

2705- VIEW NEG

2706- " "

2707- DRAWING ROOM POINTERS-
(PRINTED MATTER-)

Missing

2708- NO NEGATIVE

2709- METRIC EQUIVALENTS-

Missing

2710 - STANDARD FITS IN THE MACHINE
SHOP - FROM MACHINERY - missing

2711 - NO NEGATIVE

2712 - READING MATTER FROM MACHINERY -
PLUGS & SIZES - missing

2713 - " " " " " "

2714 - " " " " " "

2715- READING MATTER FROM MACHINERY-
PLUGS & SIZES- missing

2716- " " " " "

2717- " " " " "

2718- STANDARD BEAD & WHEEL FOR missing
EXPEDITE HEEL FINISHING MACH. XHF

2719- VIEW NEG-

2855- VIEW NEG.

2856- " "

2857- " "

2858- BOTTOM ROLL - FR-Y653

2859- VIEW NEG

2865-. VIEW NEG-

2866-. BROKEN PART OF MILLING MACH. FOR
IDENTIFICATION. SENT TO BROWN & SHARPE

2867-. VIEW NEG-

2868-. " "

2869-. " "

3005-. HEEL BREAST SCOURING WHEEL
HBS-8348 (Removed from file)

3006-. VIEW NEG

3007-. " "

3008-. " "

3009-. " "

3030-- URTC - $\frac{1}{10}$

3031-- URTC - $\frac{1}{4}$

3032-- URTC - $\frac{1}{10}$

3033-- VIEW NEG Mar-9-1911

Adjustable Cutting Block Bench.

3034-- " " Mar-9-1911

Adjustable Cutting Block Bench.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

3100 — 3499

NUMBERS FROM + INCLUDING 3100 TO 3500 ARE
TO BE KNOWN AS "B" NUMBERS AND USED
FOR THE BOXING DEPARTMENT IN CONTINUATION
OF CATALOGUE NUMBERS RUNNING FROM AND
INCLUDING 2000 TO 2199.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

3500 - 3999.

NUMBERS FROM & INCLUDING 3500 TO 3999 ARE
SUPPLEMENTARY NUMBERS TO BE USED AS
OCCASIONS MAY REQUIRE IN CONNECTION WITH
THE REGULAR NEGATIVE CATALOGUE.

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

4175-. VIEW NEG

4176-. NO NEGATIVE

4177-. VIEW NEG

4178-. " "

4179-. PO - $\frac{1}{6}$ - MOD. C

4265-. FIS - $\frac{1}{3}$

4266-. Full Size FIS,

4267-. " " "

4268-. VIEW NEG

4269-. " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

4270- VIEW NEG

4271- " "

4272- " "

4273- EIS - FULL SIZE

4274- VIEW NEG-

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

4320--SMITH SKIVER- COPY BLUEPRINT- CSMS

4321- FLUMER SKIING MACH. MOD. D. $\frac{1}{8}$ - PLU-

4322-- PLU- $\frac{1}{6}$

4323-- " $\frac{1}{6}$

4324-- " $\frac{1}{6}$

5215-. VIEW NEG.

5216-. REGENT STAMPING MACH. RPS
1/4 - MOBS. B+C-

5217-. REGENT STAMPING MACH- RPS
1/4 - MOBS. B+C-

5218-. SHOE HORN
R3355E RPS

5219-. VIEW NEG

- 5255 - APEX THIN EDGE MACH.
 MOD-A- $\frac{1}{6}$ TF
- 5256 - TAP & SOLE ROUNDING MACH.
 MOD-A- $\frac{1}{6}$ TR
- 5257 - APEX SPRING HEEL TRIMMING MACH
 MOD-A- $\frac{1}{6}$ HSH T
- 5258 - TO SHOW CHANGE IN PART FOR
 ENGRAVER - MOD. A RTP
- 5259 - ROLLING MACH - MOD-B- HPRM-
 $\frac{1}{12}$

5440.- TURNING FIXTURES FOR TURNING WOOD
RIM WHEELS (1418-β3-3)

5441- " " "

5442- " " "

5443- " " "

5444- " " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

5445.- TURNING FIXTURES FOR TURNING WOOD
RIM WHEELS. (MACH. NO. 1418- B3-3)

5446.- VIEW NEGS.

5447.- " "

5448.- " "

5449.- " "

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270

5830-. 28" SS.

PART. 02239+ FOR PLATE 5718-

5831-. РАПИД НАКЛА МЕТОД FOLDING MACH.

МОД-С. SIZE 1/12

RF

5832-. RF- SIZE 1/8

5833-. " " 1/6

5834-. " " 1/6

Part Plate

Negatives Sold up to

6601

12000 - mg - 2-23

For more information contact the Archives Center at archivescenter@si.edu or 202-633-3270